

# Veberod Gem Gallery Class Notes

## Forged Copper Bracelet

Oh what a hammer can do! We'll make this bracelet using torches and just one hammer. We'll talk about what different hammer heads do to your metal before working on this bracelet.



### Supplies Required:

22ga Copper Sheet, 2x6"

### Tools Required:

Raising Hammer (purchase required for participation): 337421 or 337418

Bench Block: 312317 or 312319

### Basic tools and supplies required for most classes:

Jeweler's sawframe: 349704

Polishing points: 310446, 310448, 311466

Clamp on benchpin: 313361

Center punch: 347900

Chain nose pliers: 346518 or 346160

Bur wax: 319928

Wire cutters: 346122 or 346209

White diamond polishing compound: 347448

Drill bits: 328565 or 328500

Rouge compound: 347416

**A note on cost of supplies** - Our classes are not kits, we try to encourage creativity. It is difficult to give even an estimate for the cost of supplies since most people have some items already, and most classes have different options. If you have never taken classes before and need everything, we will be happy to let you use whatever tools we have available for your first class so you can discover how enjoyable it can be! The one-time cost for the basic tools and supplies required for all classes after that is about \$60. In addition each class has a list of required tools and supplies. For this class that cost will run about \$60 - \$100. If you have any questions regarding the cost of supplies or anything else about the class, please contact us.